



IMPORTANT NOTICE FOR THE 70-KM GBIC TRANSCEIVER



Incorrect Recognition of 70-km GBIC in the Ethernet Detail Field

The Ethernet Detail field and Web Views incorrectly report the 70-km GBIC as 1000BaseLX (GBIC)10-km. The product (70-km GBIC) is operating correctly.